



Radiography Camera Inspection

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>
28-Jul-18		
Approved	ROLI-2	12057
04-Jul-18		
Approved	ROLI-2	16260
21-Jun-18		
Rejected	DELTA 880	D7378
	IR100	7473
21-Mar-18		
Approved	ROLI-2	12030
	ROLI-3	09064
18-Jan-18		
Rejected	DELTA 880	D9291
11-Jan-18		
Approved	ROLI-2	15201
30-Nov-17		
Approved	SPEC-150	1429
		1709
		401
28-Nov-17		
Approved	ROLI-3	11123
28-Oct-17		
Approved	ROLI-2	12005
19-Sep-17		
Approved	ROLI-2	12006
01-Aug-17		
Approved	DELTA 880	D3777
13-May-17		

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>
Approved	ROLI-3	11118
