



## Radiography Camera Inspection

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>
<b>21-Mar-18</b>		
Approved	ROLI-1 S.S.	11001
	ROLI-2	12030
		13138
		15213
		15249
		16263
		16279
		16299
	ROLI-3	09064
		10111
		11115
		12173
		14227
		17268
<b>08-Mar-18</b>		
Rejected	DELTA 880	D9952
	IR 100	7488
<b>27-Jan-18</b>		
Approved	ROLI-3	14246
<b>18-Jan-18</b>		
Rejected	DELTA 880	D9291
<b>11-Jan-18</b>		
Approved	ROLI-2	15201
	ROLI-3	12161
<b>30-Nov-17</b>		

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>
Approved	DELTA 880	D10577
	SPEC-150	1429
		1709
		401
28-Nov-17		
Approved	ROLI-3	11123
28-Oct-17		
Approved	ROLI-2	12005
19-Sep-17		
Approved	ROLI-2	12006
01-Aug-17		
Approved	DELTA 880	D3777
13-May-17		
Approved	ROLI-3	11118