



## *Radiography Camera Inspection*

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>
21-Jun-18		
Approved	IR100	7419
		7420
		7470
		7488
		7500
	ROLI-1 S.S.	11003
		11024
		11025
	ROLI-2	12018
		12020
		12027
		12050
		12051
		12052
		13097
		13109
		13110
		13111
		13130
		14157
		14170
		15220
		16251
		16271
		16302

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>		
Approved	ROLI-2	16307		
		16333		
		16379		
		16382		
		16399		
		16420		
		08033		
	ROLI-3	09060		
		12178		
		14259		
		17264		
		Rejected	DELTA 880	D7378
			GAMMAMAT	659
			IR100	7430
7473				
7501				
05-Jun-18	ROLI-2	12042		
Approved		12055		
		12060		
		12073		
		12082		
		12085		
		13149		
		14153		
		14163		
		14193		
		14194		
		15207		
		15218		
		15225		

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>	
Approved	ROLI-2	15226	
		15230	
		15234	
		16266	
		16277	
		16294	
		16308	
		16313	
		16319	
		16376	
		16385	
		16389	
		16393	
		16414	
		17427	
		17435	
		17436	
		ROLI-3	09066
			10106
	11126		
12161			
12163			
12174			
12180			
13204			
14233			
17272			
21-Mar-18	Approved	ROLI-2	12030
08-Mar-18		ROLI-3	09064

<i>camera_Inspection_Status</i>	<i>Camera_Type</i>	<i>Camera_Sl_No</i>
Approved 18-Jan-18	DELTA 880	D5412
Rejected 11-Jan-18	DELTA 880	D9291
Approved 30-Nov-17	ROLI-2	15201
Approved	SPEC-150	1429
		1709
		401
28-Nov-17		
Approved 28-Oct-17	ROLI-3	11123
Approved 19-Sep-17	ROLI-2	12005
Approved 01-Aug-17	ROLI-2	12006
Approved 13-May-17	DELTA 880	D3777
Approved	ROLI-3	11118